



C9C
MT

I hereby certify that this correspondence
is being deposited with the United States
Postal Service as first class mail in an
envelope addressed to:

Commissioner for Patents
United States Patent & Trademark Office
Mail Stop: Certificate of Correction
P.O. Box 1450
Alexandria, VA 22313-1450, on 3/16/05

Michael P. Pinianni
DATE March 16, 2005

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Examiner: Basil S. Katcheves

Group Art Unit: 3635

In re application of

Paul W. Brown

Serial No.: 10/044,660

Filed: January 19, 2002

Patent No. 6,810,634 B1

Issued: November 2, 2004

Certificate
MAR 24 2005
of Correction

: METHOD OF RESISTING CORROSION
: IN METAL REINFORCING ELEMENTS
: CONTAINED IN CONCRETE AND
: RELATED COMPOUNDS AND
: STRUCTURES

: ATTORNEY DOCKET: 287122-00001-1

03/21/2005 HDEHESS1 00000010 022556 6810634

01 FC:1811 100.00 DA

LETTER

600 Grant St., 44th Floor
Pittsburgh, PA 15219
March 16, 2005

Commissioner for Patents
United States Patent & Trademark Office
Certificate of Correction Branch
Mail Stop: Certificate of Correction
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

In comparing the above-identified original patent document with the original
papers filed in the Patent and Trademark Office, we have noted twelve (12)

typographical errors which should be charged to our Deposit Account No. 02-2556 in the amount of One Hundred Dollars (\$100).

It is respectfully requested that a Certificate of Correction be issued to correct these printing errors in the above-identified patent.

Respectfully submitted,

A handwritten signature in black ink, reading "Tara L. Pfaeffle", followed by a horizontal line extending to the right.

Tara L. Pfaeffle

Registration No. 52,605

Attorney for Applicant

(412) 566-5941

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,810,634 B1

DATED : November 2, 2004

INVENTOR(S) : Paul W. Brown

It is certified that errors appear in the above-identified patent and that said Letters Patent should be corrected as shown below:

Col. 1, line 50, after "sea walls", insert a ---.

Col. 3, line 47, delete "to" prior to "provide".

Col. 3, line 65, "rehabilitated through by sequestering" should read --rehabilitated by sequestering--.

Col. 4, line 7, "invention and facilitates" should read --invention facilitates--.

Col. 6, line 48, "seal" should read --steel--.

Col. 7, line 23, after "presence", insert --of--.

Col. 8, line 10, after "presence", insert --of--.

Col. 9, line 62, "Referred" should read --Referring--.

1 of 2

MAILING ADDRESS OF SENDER:

Sally Novosel, Docket Administrator
ECKERT SEAMANS CHERIN & MELLOTT, LLC
600 Grant Street, 44th Floor
Pittsburgh, PA 15219

PATENT NO. 6,810,634

No. of add'l. copies

@ 50¢ per page

⇒

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,810,634 B1

DATED : November 2, 2004

INVENTOR(S) : Paul W. Brown

It is certified that errors appear in the above-identified patent and that said Letters Patent should be corrected as shown below:

Col. 10, line 36, "structural" should read --structure will--.

Col. 11, line 13, "NaAlO₄" should read --NaAlO₂--.

Col. 11, lines 15 and 19, "2NaAlO₄" should read --2NaAlO₂--.

2 of 2

MAILING ADDRESS OF SENDER:

Sally Novosel, Docket Administrator
ECKERT SEAMANS CHERIN & MELLOTT, LLC
600 Grant Street, 44th Floor
Pittsburgh, PA 15219

PATENT NO. 6,810,634

No. of add'l. copies

@ 50¢ per page

⇒